ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0465, W0522, W0437, W0518, W0461, W0463, W0459, W	NA, Shetty Lyt, 1st Main Rd, Shetty Lyt, 2nd Main Rd, 6th Crs, Shetty Lyt, 4th Main Rd	Surabhi lauout 1st main and cross road
Segment No.	**Total Length (m)**	
1/S-W0465/S115506	306.62	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.67	77.599526	13.092600	77.599521	13.093130	W0522	W0518
2	177.96	77.599271	13.092558	77.600907	13.092670	W0437	M0013
3	69.99	77.600736	13.092610	77.600821	13.091983	W0522	M0013

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Asphalting and Improvements to Roads at Surabhi lauout 1st main and cross road in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	4500000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Asphalting and Improvements to Roads at Surabhi lauout 1st main and cross road in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	001-17-000035
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D)/WO/133/2017 -18	31/03/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2017	29/04/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

Asst. Executive Engineer
Yelahanka Division
(BBMP)
Yelahanka, Bangalore

8863065

eld Inspection Details

Number of Trees	Any Other Information	Name
18		SACHIN
Date of Inspection	**Remarks**	
23/05/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0465, W0522, W0437, W0518,

Asst. Executive Engineer

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	23/05/2017	21/06/2017	COMPLETED
SE	VASU K M	23/05/2017	21/06/2017	COMPLETED
EE	VASU K M	23/05/2017	21/06/2017	COMPLETED
AEE	DEVARAJ	23/05/2017	21/06/2017	COMPLETED
AE	SACHIN	23/05/2017	21/06/2017	COMPLETED
AE	SACHIN	22/05/2017	21/06/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0465, W0522, W0437, W0518,

Asst. Executive Engineer
Yelahanka Sub.